

# National Transportation Safety Board Aviation Accident Data Summary

Location: Orlando, FL Accident Number: ATL00LA050

 Date & Time:
 05/02/2000, 1913 EDT
 Registration:
 N56LW

 Aircraft:
 Cessna 501
 Injuries:
 2 None

Flight Conducted Under: Part 91: General Aviation - Personal

## **Analysis**

While en route to land, the pilot silenced the landing gear warning horn. Just prior to touch down, the pilot attempted to lower the landing gear. The airplane touched down with the landing gear in transit, and the right landing gear collapsed. The examination and the functional check of the airplane failed to disclose a mechanical problem with the landing gear extension and retraction system. The pilot also did not report a mechanical problem with the airplane. The pilot stated that he forgot to lower the landing gear, as stated in the normal pre-landing checklist.

#### **Probable Cause**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to follow the landing checklist that resulted in the delay of lowering the landing gear before touchdown.

## **Findings**

Occurrence #1: WHEELS UP LANDING Phase of Operation: LANDING

#### **Findings**

1. (C) CHECKLIST - NOT FOLLOWED - PILOT IN COMMAND 2. (C) LANDING GEAR - DELAYED - PILOT IN COMMAND

#### **Pilot Information**

Certificate:	Private	Age:	57
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Instrument Rating(s):	Airplane
Other Aircraft Rating(s):	None	Instructor Rating(s):	None
Flight Time:	3132 hours (Total, all aircraft), 776 hours (Total, this make and model), 2279 hours (Pilot In Command, all aircraft), 27 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

# Aircraft and Owner/Operator Information

Aircraft Manufacturer: Cessna Registration: N56LW 501 Model/Series: **Engines:** 2 Turbo Jet Operator: Larry M. Phillips **Engine Manufacturer:** Pratt & Whitney Operating Certificate(s) **Engine Model/Series:** JT15D-1A None Held:

Flight Conducted Under: Part 91: General Aviation - Personal

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	MCO, 96 ft msl	Weather Information Source:	Weather Observation Facility
Lowest Ceiling:	None	Wind Speed/Gusts, Direction:	9 knots, 100°
Temperature:	24°C	Visibility	10 Miles
Precipitation and Obscuration:			
Departure Point:	Leesburg, FL (LEE)	Destination: Orlando, FL (MC	0)

#### **Airport Information**

Airport: Orlando International Airport (MCO) Runway Surface Type: Concrete

Runway Used: 18R Runway Surface Condition: Dry

Runway Length/Width: 12000 ft / 200 ft

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Latitude. Longitude:	28.428889, -81.316111		

#### **Administrative Information**

Investigator In Charge (IIC):	Phillip Powell	Adopted Date:	09/30/2003
Investigation Docket:		are publicly availab	chival information for the NTSB's investigations. le from the NTSB's Record Management Division after this date are available at

Page 2 of 2 ATL00LA050

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.