

ICE CRYSTAL ICING & HOT TOWERS

John Salamankas

Ice Crystal Icing & Hot Towers



- **“Hot Towers” presented to CAB in 2007**
 - **Gulfstream encounters described and analyzed**
- **“Ice Crystal Icing” addressed in 2008**
 - **Data base of air carrier encounters**
 - **Few Gulfstream encounters**
- **Both topics presented numerous times**
 - **Question arose**
- **Are these hot tower encounters or not?**
 - **If not, what?**

Hot Towers or Not

Definition



- **NASA definition: “Towering rain cloud that reaches the top of the tropopause”**
- **Associated with tropical cyclones and hurricanes**
- **Occur between 36° N and 36° S latitude**
- **Diameter up to 3½ miles**
- **Duration ½ to 2 hours**
- **Size and duration make them difficult to study**
- **Useful predictors of hurricane growth**

Tropical Rainfall Measurement Mission



Place mouse pointer on map and right click to play movie clip





- **FL410 over equatorial Africa**
 - Scattered thunderstorms below
 - Cirrus cloud, light turbulence, SAT -63°C
- **A/T disconnect, CAS messages**
- **SAT at -48°C continued warming to -26°C**
- **EPR indicated low, Mach reduced to .67**
- **After 22 minutes, temperature rapidly returned to -56°C**
- **All systems normal**



- **Second event, over the Pacific**
- **Weather conditions and aircraft reaction similar**
- **Engine vibration developed to exceedance levels**
 - **Engine to idle, reversed course to exit conditions**
 - **Set course for alternate and descended**
- **Vibration diminished during descent, gone at 15,000'**
- **Engines inspected - completely normal**



- **FL410, Pacific ocean near equator**
 - Scattered thunderstorms below
 - Light turbulence, cirrus cloud, -63°C
- **A/T disconnect, “L-R Eng Backup Air Data”, “MADC Miscompare”**
- **SAT -48°C continued warming to -24°C**
- **Altimeters and Mach indications all disagreed.**
- **Slow descent after speed decayed**
- **After 25 minutes temperature rapidly returned to -56°C**



- **High altitude, ISA or colder temperatures**
- **Heavy moisture in lower altitudes**
- **Nearby convective activity**
 - **No radar returns at event location**
- **In cirrus cloud**
- **Light to moderate turbulence**
- **TAT probe anomaly**



- **Convective activity lofts ice crystals in significant quantities into the upper atmosphere**
 - Ice crystals, not liquid water
- **Invisible to aircraft radar and ice detectors**
- **No airframe icing**
- **Crews unaware of potential hazards**
- **Greatest hazard is loss of engine power**
- **150 air carrier events in FAA/Industry data base**



- **Ice crystals previously though harmless**
- **Theory – bounced off airframe and engine surfaces**
- **Reality – crystals melt due to compression effects**
 - **Pass through fan section**
 - **Enter core and melt on warm surfaces**
 - **Moisture traps additional crystals**
 - **Ice builds up, sheds into compressor**
 - **Engine surges, rolls back, and flames out**



- **No engine can be considered immune**
- **Engine susceptibility varies with design**
 - **Blade arrangement and geometry**
 - **Engine control technology**
 - **Variable bleed valve scheduling**
- **Events have driven AD's and AFM changes**
 - **CF6-80 engine on B747, B767, and MD-11**
 - **Engine anti-ice ON any time TAT 10° or lower**
 - **Beechjet (Hawker 400XP) dual engine flameouts**
 - **Engine anti-ice ON during high altitude flight in the vicinity of visible moisture and convective activity**

Hot Towers or Not Gulfstream Ice Crystal Events



- **2007 report by a GIV of high engine vibration in VMC conditions during an enroute descent**
 - Had flown in vicinity of strong convective activity for a long time
 - Fan blade icing suspected
- **GV report of high EVM during VMC descent**
 - Airplane had just exited IMC
 - Fan blade icing suspected
- **G550 reported high EVM during VMC descent**
 - Flew over thunderstorms in tropical storm system
 - Fan blade icing suspected

Hot Towers or Not Gulfstream Ice Crystal Events



- **GIV dual engine flameout in 1991**
 - In vicinity of a huge convective storm
 - Surrounded by towering cumulus
- **Both engines were successfully restarted**
- **FDR analysis showed abnormal TAT indications prior to the event**
- **Report attributed flameout to heavy water ingestion**
- **In retrospect, ice crystal icing should be considered as the probable cause**



- FAR 25 requires flight testing in natural icing
- Equipment and Systems – Perform their intended function under any foreseeable operating conditions
- Airplane – Safely operate in “continuous maximum” and “intermittent maximum” icing
- Engines – Operate throughout flight power range, including idle, with no adverse effects from ice accretion
- “Maximum Icing” defined by
 - Liquid water content
 - Droplet size



- **“Continuous Maximum” – difficult to find**
 - **Narrow altitude bands**
 - **Small temperature range**
 - **Total temp below freezing**
 - **-8°C Ideal**
 - **-13°C Snow**
 - **-20°C Solid**
- **Testing performed in moisture laden stratus clouds below 20,000 ft.**
- **No exposure to ice crystals**



- **High altitude, ISA or colder temperatures**
- **Heavy moisture in lower altitudes**
- **Nearby convective activity**
 - **No radar returns at event location**
- **In or just exited cloud**
- **Light to moderate turbulence**
- **TAT probe anomaly**



- **High altitude, ISA or colder temperatures**
- **Heavy moisture in lower altitudes**
- **Nearby convective activity**
 - **No radar returns at event location**
- **In cirrus cloud**
- **Light to moderate turbulence**
- **TAT probe anomaly**



- **Cause and effect explanations not equally credible**
- **Engine ice crystal icing explained by basic physics**
 - **Large data base of similar events**
 - **FDR data studied**
 - **P&W/FAA confirmation by flight test**
- **Experience and understanding have resulted in more stringent icing certification requirements**
 - **FAR 25 adding *Large* super cooled droplet icing**
 - **FAR 33 adding *Ice Crystal* and *Mixed Phase* icing**

Hot Towers or Not



- **Hot towers are real, but are the encounters?**
- **Parcel - environment temperature difference is a measure of updraft severity**
 - **4°C Strong**
 - **5°C to 7°C Severe**
 - **30°C “Unprecedented”**
- **Events report only light to moderate chop**
- **No reports from inside top of towering CB**
- **Encounters of :20 to :25 minutes span up to 200nm**

Tropical Rainfall Measurement Mission



Place mouse pointer on map and right click to play movie clip





- **Temp rise *assumed* due to hot tower**
 - Is the indication correct?
 - Could there be another cause?
- **Focus on Total Temperature Sensor**
 - Gulfstream probes same as Boeing & many others
 - Identical externally
 - Minor internal variations by PN
 - Heater current type
 - Base plate contour
 - Connector type

Hot Towers or Not Goodrich Total Temp Probe







Hot Towers or Not Goodrich Total Temp Probe



- **Review of sensor specs and fault history**
 - High MTBR
 - 60% heater failures, 2% sensor failures
- **Part Number change for PlaneView aircraft**
 - Performance enhanced in extreme icing conditions
 - Inlet scoop change to reduce *clogging by ice crystals*
 - Improved internal heat conduction to critical surfaces
 - Increased heater power
- **No Hot Tower reports from PlaneView aircraft**

Hot Towers or Not

Probe Enhancements



102LA2AG

102LK2AG

102LA2AG

102LK2AG

Hot Towers or Not Goodrich Total Temp Probe



- **Goodrich engineering confirmed**
 - Ice crystals can overwhelm heater and clog probe
 - Reduced airflow allows heater to warm sensor
 - Sensor may read 0°C, ice point of melting crystals
 - 0°C reported numerous times in airline data base
 - Rapid return to normal is consistent with heater clearing ice from probe
- **Probes became logical suspects in tower events**
- **Suspicion only, confirmation needed**



- **NOAA weather research GIV experienced several unexplained temperature increases at high altitude**
- **Aircraft records data from numerous sensors**
 - **Production standard total temp probe**
 - **Scientific temperature probes (2)**
 - **Dewpointers**
- **During some hot tower type events**
 - **Only two of the three temp probes reacted**
 - **Third probe continued to indicate normally**
 - **Dewpointers showed large increase in water vapor**



- **Recent events (Continued)**
 - Dewpointer temperatures increased first
 - Dewpointer temperature was warmer than probes
 - Considered “meteorologically incorrect”
- **Flight Meteorologist is investigating**
 - “..has to be something going on to cause this around the tops of thunderstorms”
 - Important meteorological concept
 - Safety implications
- **The answer to one question may hold the key**

Hot Towers or Not



- **If the air was really warmer –**

Why didn't all three probes indicate a hot tower?



Investigation has raised new questions

- **What caused the self-clearing engine vibrations**
 - Ice shedding procedure not used
- **During one event, only one engine vibrated**
- **Did ice crystals affect the engines and not the TAT**
- **Why didn't we know about probe icing**
 - How much of a problem is it
- **Some Gulfstream events included pack overheats**
 - Is ECS affected by ice crystals
- **Why is the temperature in the tower often near -26°C**
 - Typical temp rise between SAT and TAT at M.80

Hot Towers or Not



- **Title question may be answered**
 - **Towers are real**
 - **Encounters probably aren't**

Questions