FAA LOA D095 / D195 Status

Summary of FAA Briefing at MMEL IG Meeting 30 November 2017

Rick Ackerson - 01 December 2017



Background

- ICAO does not recognize MMEL as MEL
 - Some FAA Part 91 operators have been subjected to findings by EASA during SAFA checks in Europe
 - EASA follows ICAO guidelines No mechanism within ICAO / EASA regulations for MEL without LOA for specific aircraft serial number
- Joint FAA / EASA working group established
 - Member of this group provided briefing to MMEL IG on 30 November 2017
 - SAFA findings have been halted until FAA and EASA can resolve differences



Operator Responsibilities

- New Notice and InFO expected December 2017
- Part 91 operators will have two options
 - LOA D095 will be issued for domestic only operators
 - LOA D195 will be issued for domestic / international operators
 - International operations will require LOA D195
 - FAA review anticipated to be less scrutinous than traditional air carrier D195 approvals
 - Domestic operators may obtain LOA D195 in lieu of D095



Operator Responsibilities (Cont.)

- All Part 91 operators will have to obtain new LOA's, even if in possession of either LOA now.
 - Administrative requirement for accounting purposes at FAA
- 12 month grace period for the new LOA's to be issued after Notice and InFO are published
 - EASA expected to resume enforcement after the end of the grace period



FAA Responsibilities

- PL 34 for domestic operators and PL 36 for international operators to be revised
- Order 8900 Ch 4 to be updated
- AC 91-67 was cancelled in November 2017
 - Did not follow ICAO guidelines
 - Will be revised and re-published when this process is complete



Thank You

PROPRIETARY NOTICE

THIS DATA AND INFORMATION CONTAINED HEREIN IS PROPRIETARY DATA OF GULFSTREAM AEROSPACE CORPORATION. NEITHER THIS DATA NOR THE DATA CONTAINED HEREIN SHALL BE REPRODUCED, USED, OR DISCLOSED TO OTHERS WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF GULFSTREAM AEROSPACE CORPORATION.

